Qa Department Name	Status Code	T3 Id	Vin	Creation Timestamp	Creation Timestamp2	Opened Date	Closed Date
QABody	INITIATED	TA081330001	JTHCK262X72[redacted]	12-May-08	5/12/2008 4:25	12-May-08	01-JAN-0001
QABody	INITIATED	TA081350318	4T1BK46K39U[redacted]	14-May-08	5/14/2008 13:12	14-May-08	01-JAN-0001
QABody	INITIATED	TA081360031	JTMZK32V286[redacted]	15-May-08	5/15/2008 7:07	15-May-08	01-JAN-0001
QABody	INITIATED	TA081360198	4T4BE46K48R[redacted]	15-May-08	5/15/2008 11:28	15-May-08	01-JAN-0001
QABody	INITIATED	TA081370247	JTHBK262082[redacted]	16-May-08	5/16/2008 13:06	16-May-08	01-JAN-0001
QABody	INITIATED	TA081370308	JTNBB46K473[redacted]	16-May-08	5/16/2008 15:13	16-May-08	01-JAN-0001
QAChassis	INITIATED	TA081330068	4T1CA38P14U[redacted]	12-May-08	5/12/2008 7:49	12-May-08	01-JAN-0001
QAChassis	INITIATED	TA081330122	JTHBL46F875[redacted]	12-May-08	5/12/2008 9:23	12-May-08	01-JAN-0001
QAChassis	INITIATED	TA081330135	JTHBP262685[redacted]	12-May-08	5/12/2008 9:39	12-May-08	01-JAN-0001
QAChassis	INITIATED	TA081330283	4T1BE46K57U[redacted]	12-May-08	5/12/2008 12:53	12-May-08	01-JAN-0001
QAChassis	INITIATED	TA081330337	JTHBL46F775[redacted]	12-May-08	5/12/2008 14:04	12-May-08	01-JAN-0001
QAChassis	INITIATED	TA081340052	JTHBJ46GX72[redacted]	13-May-08	5/13/2008 7:10	13-May-08	01-JAN-0001
QAChassis	INITIATED	TA081340098	2T2GA31U05C[redacted]	13-May-08	5/13/2008 8:06	13-May-08	01-JAN-0001
QAChassis	INITIATED	TA081340315	5TELU42N66Z[redacted]	13-May-08	5/13/2008 13:12	13-May-08	01-JAN-0001
QAChassis	INITIATED	TA081340381	4T1BK36B67U[redacted]	13-May-08	5/13/2008 14:41	13-May-08	01-JAN-0001
QAChassis	INITIATED	TA081350179	JTDBL40E29J[redacted]	14-May-08	5/14/2008 10:04	14-May-08	01-JAN-0001
QAChassis	INITIATED	TA081350241	JTHBE262165[redacted]	14-May-08	5/14/2008 11:23	14-May-08	01-JAN-0001
QAChassis	INITIATED	TA081370153	JTDKB20UX77[redacted]	16-May-08	5/16/2008 9:54	16-May-08	01-JAN-0001
QAChassis	INITIATED	TA081370208	JTMBD32V366[redacted]	16-May-08	5/16/2008 11:40	16-May-08	01-JAN-0001
QAChassis	INITIATED	TA081380006	4T1BE46K87U[redacted]	17-May-08	5/17/2008 16:34	17-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081330003	JTDKB20UX63[redacted]	12-May-08	5/12/2008 5:03	12-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081330005	2T2HK31U97C[redacted]	12-May-08	5/12/2008 5:34	12-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081330030	4T1BK36B98U281535	12-May-08	5/12/2008 6:41	12-May-08	01-JAN-0001

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Last Modified Timestamp	Repair Mileage	Dtc Code	Model Name	Model Year	Dealer Code
5/12/2008 4:25	11,807		IS250	2007	62901
5/14/2008 13:12	2	B2344	Camry	2009	13033
5/15/2008 7:07	2,488		RAV4	2008	12143
5/15/2008 11:28	6,915		Camry	2008	12134
5/16/2008 13:06	3,572		IS250	2008	60906
5/16/2008 15:13	15,771		Camry HV	2007	4189
5/12/2008 7:49	13,636	C1231	Solara	2004	45073
5/12/2008 9:23	10,012		LS460	2007	63231
5/12/2008 9:39	129		IS F	2008	60402
5/12/2008 12:53	30,135		Camry	2007	22035
5/12/2008 14:04	14,753		LS460	2007	60448
5/13/2008 7:10	45,028		ES350	2007	60906
5/13/2008 8:06	20,321		RX330	2005	60906
5/13/2008 13:12	30,709		Tacoma	2006	29099
5/13/2008 14:41	16,413		Avalon	2007	4017
5/14/2008 10:04	563		Corolla	2009	4134
5/14/2008 11:23	12,996		IS350	2006	60417
5/16/2008 9:54	17,231		Prius	2007	2036
5/16/2008 11:40	32,393	P1578	RAV4	2006	48005
5/17/2008 16:34	35,952		Camry	2007	4282
5/12/2008 5:03	33,053		Prius	2006	41043
5/12/2008 5:34	10,000		RX350	2007	62630
5/12/2008 6:41	3,766		Avalon	2008	24077

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Region Short Name	Region Short Name2	District Code	Status Code	Owner Name	Repair Date	Service Category Desc
EAS	EAS	5	INITIATED	FRANK HILLER	4/21/2008 0:00	Vehicle Interior
CHI	CHI	4	INITIATED	ROGER CRAFT	5/14/2008 0:00	Vehicle Exterior
CHI	CHI	6	INITIATED	KYLE BROADRICK	5/15/2008 0:00	Vehicle Interior
CHI	CHI	2	INITIATED	JOHN VITUG	5/13/2008 0:00	Vehicle Interior
SOU	SOU	4	INITIATED	CHRIS HARRELL	5/15/2008 0:00	Vehicle Interior
SFR	SFR	2	INITIATED	RICARDO LOPEZ	5/16/2008 0:00	Vehicle Interior
CAT	CAT	10	INITIATED	LYNN YODER	5/12/2008 0:00	Steering
SOU	SOU	5	INITIATED	BRYAN SMITH	5/12/2008 0:00	Brake
WES	WES	2	INITIATED	ROBERT JERSEY	5/12/2008 0:00	Brake
CHI	CHI	9	INITIATED	JEFFREY HENRICKSON	5/5/2008 0:00	Vehicle Interior
WES	WES	3	INITIATED	KENNETH SMITH	5/12/2008 0:00	Brake
SOU	SOU	4	INITIATED	CARLOS SANCHEZ	5/13/2008 0:00	Brake
SOU	SOU	4	INITIATED	RICHARD LOUGHMAN	5/13/2008 0:00	Steering
NYR	NYR	5	INITIATED	DAVE MONAHAN	5/13/2008 0:00	Suspension
SFR	SFR	7	INITIATED	TIMOTHY STACEY	5/12/2008 0:00	Steering
LOS	LOS	9	INITIATED	JORGE SOLISJR	5/14/2008 0:00	Brake
WES	WES	3	INITIATED	JAMES HOESKE	5/6/2008 0:00	Brake
DEN	DEN	1	INITIATED	JOHN GUSTAFSON	5/13/2008 0:00	Brake
CHI	CHI	10	INITIATED	NICHOLAS BERTINO	5/16/2008 0:00	Brake
LOS	LOS	9	INITIATED	GLENN BAUGH	5/16/2008 0:00	Brake
CIN	CIN	J	INITIATED	CHRIS CONNER	5/12/2008 0:00	Vehicle Exterior
CEN	CEN	4	INITIATED	CHASE DILLEY	5/12/2008 0:00	Vehicle Interior
KCY	KCY	2	INITIATED	JOSHUA AXTETTER	5/8/2008 0:00	Vehicle Interior

TOY-TQ001-00034740

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Section Desc	Sub Component Desc	Condition Desc
Interior Panels/Trim	Dash Assembly/Components	Noise-squeak/rattles
Sliding Roof/Convertible	Sunroof/Wind Deflector	Inoperative
Interior Panels/Trim	Dash Assembly/Components	Noise-squeak/rattles
Seat	Fabrics	Comfort/feel
Mirror (int)	Inner Rear View Mirror	Gap/Poor Fit/Loose/Tolerance
Interior Panels/Trim	Center Console/ Box	Noise-squeak/rattles
Steering Column	Unknown	Unspecified
Brake (front)	Brake Pad	Design/Less Than Expectation
Brake (rear)	Unknown	Noise-Abnormal
Meter/Gauge/Display	Warning Light - ABS	MIL/Warning Light ON
Brake Control/Dynamic Control System	Unknown	Noise-wind noise/whistle
Brake (front)	Brake Rotor	Vibration
Steering Column	Telescopic	Inoperative
Tire/Wheel	Wheel, Alloy/Cover	Appearance Concern
Steering Column	Unknown	Noise-Abnormal
Brake System	Brake Pedal	Condition-Not-Listed
Brake (front)	Unknown	Noise-squeak/rattles
Brake (front)	Unknown	Noise-Abnormal
Brake Control/Dynamic Control System	Unknown	MIL/Warning Light ON
Brake System	Unknown	Condition-Not-Listed
Lighting (ext)	Headlight	Abnormal Operation
Theft Deterrent/Keyless Entry	Switch	Inoperative
Theft Deterrent/Keyless Entry	Smart Key/Card	Unspecified

TOY-TQ001-00034741

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Case Condition
customer not satisfied with noise level of dash, says noise is intermittant.
auto tilt down automaticaly opens back up
rattle noise heard at lower speeds, below 40mph. noise appears to be coming from behind the radio. light rattle noise; plastic sounding.
lumpy portion on both front seats by seam in the middle / around 3 inches front the front part of the seat / compared to a couple more "le" camry / showed the same thing on both front seats /
mirror tips downward when playing loud music
customer reports there is a squeak noise that sounds like it is coming from the center console area bt drivers leg area - is heard the best on rough roads. customer hears the noise about 90% of the times. sometimes it will not be there until he hits a bump or if his leg bumps the trim then it will start. nv005-07 applies
steering angle sensor has been diagnosed and replaced 3 times. problem seems resolved for 5 months or so and then returns. currently, the sas has s short circuit in it but is something else causing this to happen?
we resurfaced both ft rotors at 8k miles for vibration while braking. now cust is back w/ ft brakes almost metal to metal. and rear 1mm from touching sensor.
loud squeel form rear brakes.
brake/abs/tirepress/nowipers/ts/inop/with/wiper/on/batt/light flashes at times
multiple clicking noise heard when depressing brake pedal
cust states there is a shimie when applying the brakes
wheel will not telescope out when inserting key, no dtc's unable to duplicate
delamination of alloy wheels. pitting
clunk from area around column and intermediate shaft
found brake pedal after few seconds start going to the floor, and vehicle moves. cuase by bad master cylinder, internal leak from primary piston to secondary chamber.fix it with a new master cylinder. road test vehicle, normal stops ,no more leak on brakes.....
client states there is a squeak when braking. confirmed noise.
car has a grinding noise coming from the rh front when cold under light to medium braking. replaced front rotors & pads, bled air from brake system, connected chassis ear & road tested. noise loudest at rh strut. replaced strut & support, noise still there. only have about a 10 minute window to diagnose before noise goes away until next morning.
no start some times not all the time. if it doesn't start and you move the shift lever or hit the brake then it starts
brake pedal pulsation
left front headlight will cut off after 10 to 15 minutes of use have replaced ecu/ballast on headlight assy and have also replaced light bulb
ignition is locked and will not turn to start the car, or turn in the acc position
customer says vehicle will not start. customer says that this has happended a few times, and states that the ingition button seems stiff. when checked vehicle starts every time, no codes are present. returned vehicle to customer, then customer had it towed back in that night, however when checked the vehicle starting operation is once again normal. have checked starting operation over an extended period of time both hot and cold, and have not once been able to reproduce the no start condition.

TOY-TQ001-00034742

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Suggestion	Repair	Division Name	Creator Name	Original Owner	Dealer Tech Initiated	Dealer Tech Name
		LEXUS	FRANK HILLER		y	HILLER, FRANK
		TOYOTA	ROGER CRAFT		y	CRAFT, ROGER
		TOYOTA	KYLE BROADRICK		y	BROADRICK, KYLE
		TOYOTA	JOHN VITUG		y	VITUG, JOHN
		LEXUS	CHRIS HARRELL		y	HARRELL, CHRIS
		TOYOTA	RICARDO LOPEZ		y	LOPEZ, RICARDO
		TOYOTA	LYNN YODER		y	YODER, LYNN
		LEXUS	BRYAN SMITH		y	SMITH, BRYAN
		LEXUS	ROBERT JERSEY		y	JERSEY, ROBERT
		TOYOTA	JEFFREY HENRICKSON		y	HENRICKSON, JEFFREY
		LEXUS	KENNETH SMITH		y	SMITH, KENNETH
		LEXUS	CARLOS SANCHEZ		y	SANCHEZ, CARLOS
		LEXUS	RICHARD LOUGHMAN		y	LOUGHMAN, RICHARD
		TOYOTA	DAVE MONAHAN		y	MONAHAN, DAVE
		TOYOTA	TIMOTHY STACEY		y	STACEY, TIMOTHY
		TOYOTA	JORGE SOLISJR		y	SOLISJR, JORGE
		LEXUS	JAMES HOESKE		y	HOESKE, JAMES
		TOYOTA	JOHN GUSTAFSON		y	GUSTAFSON, JOHN
		TOYOTA	NICHOLAS BERTINO		y	BERTINO, NICHOLAS
		TOYOTA	GLENN BAUGH		y	BAUGH, GLENN
		TOYOTA	CHRIS CONNER		y	CONNER, CHRIS
		LEXUS	CHASE DILLEY		y	DILLEY, CHASE
		TOYOTA	JOSHUA AXTETTER		y	AXTETTER, JOSHUA

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Dealer Name	Qa Department Name	Cause Component Desc	Cause Sub Comp Desc	Cause Condition Desc
LEXUS OF CHERRY HILL	QABody			
TOM WOOD TOYOTA	QABody			
O'BRIEN TOYOTA OF URBANA	QABody			
OAKBROOK TOY. IN WESTMONT	QABody			
LEXUS OF ORLANDO	QABody			
TOYOTA OF WALNUT CREEK	QABody			
BROWN'S CHARLOTTESVILLE	QAChassis			
JOHNSON LEXUS OF DURHAM	QAChassis			
LONGO LEXUS	QAChassis			
MAPLEWOOD TOYOTA	QAChassis			
LEXUS OF STEVENS CREEK	QAChassis			
LEXUS OF ORLANDO	QAChassis			
LEXUS OF ORLANDO	QAChassis			
TOYOTA OF TURNERSVILLE	QAChassis			
JIMMY VASSER TOYOTA	QAChassis			
ROGERS & ROGERS TOYOTA	QAChassis			
LEXUS OF SERRAMONTE	QAChassis			
CAMELBACK TOYOTA	QAChassis			
LE MIEUX & SON TOYOTA	QAChassis			
TOYOTA OF ESCONDIDO	QAChassis			
PERFORMANCE TOYOTA	QAElectrical			
LEXUS OF LINCOLN	QAElectrical			
JAY WOLFE TOYOTA OF W CTY	QAElectrical			

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Repair Order Num	Ta Case Priority
266352	NORMAL
203966	NORMAL
481560	NORMAL
489401	NORMAL
94799	NORMAL
748528	NORMAL
378749	NORMAL
243778	NORMAL
94954	NORMAL
382054	NORMAL
89331	NORMAL
94185	NORMAL
94336	NORMAL
91702	NORMAL
11418	NORMAL
112998	NORMAL
358430	NORMAL
652387	NORMAL
117847	NORMAL
400081	NORMAL
618275	NORMAL
32819	NORMAL
90314	NORMAL

TOY-TQ001-00034745

QAElectrical	INITIATED	TA081330091	4T1BE46K07U[redacted]	12-May-08	5/12/2008 8:23	12-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081330322	JTDKB20U883[redacted]	12-May-08	5/12/2008 13:42	12-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081330335	JTDKB20U883[redacted]	12-May-08	5/12/2008 14:04	12-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081330397	JTEES42AX82[redacted]	12-May-08	5/12/2008 16:06	12-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081340005	4T1BB46K89U[redacted]	13-May-08	5/13/2008 5:46	13-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081340160	5TDBA23C45S[redacted]	13-May-08	5/13/2008 9:34	13-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081340313	JTNBB46K973[redacted]	13-May-08	5/13/2008 13:07	13-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081350024	4T1BK46K59U[redacted]	14-May-08	5/14/2008 6:21	14-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081350176	5TBBV58198S[redacted]	14-May-08	5/14/2008 9:56	14-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081360136	JTJHA31U550[redacted]	15-May-08	5/15/2008 9:35	15-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081360266	5TDZK23C57S[redacted]	15-May-08	5/15/2008 12:52	15-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081360269	4T1BK36B18U[redacted]	15-May-08	5/15/2008 12:55	15-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081370193	1NXBR32E14Z[redacted]	16-May-08	5/16/2008 11:12	16-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081370214	JTHBE96S970[redacted]	16-May-08	5/16/2008 11:57	16-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081370315	JTDBE30K840[redacted]	16-May-08	5/16/2008 15:54	16-May-08	01-JAN-0001
QAElectrical	INITIATED	TA081380005	5TETX22N37Z[redacted]	17-May-08	5/17/2008 16:08	17-May-08	01-JAN-0001
QAHybrid	INITIATED	TA081340055	JTDKB20U283[redacted]	13-May-08	5/13/2008 7:14	13-May-08	01-JAN-0001
QAHybrid	INITIATED	TA081340137	JTJHW31U160[redacted]	13-May-08	5/13/2008 9:06	13-May-08	01-JAN-0001
QAHybrid	INITIATED	TA081350173	JT2BK18U030[redacted]	14-May-08	5/14/2008 9:53	14-May-08	01-JAN-0001
QAHybrid	INITIATED	TA081350266	JTJHW31U260[redacted]	14-May-08	5/14/2008 12:00	14-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081330175	1NXBR32E06Z[redacted]	12-May-08	5/12/2008 11:04	12-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081330184	5TDBA22C94S[redacted]	12-May-08	5/12/2008 11:10	12-May-08	01-JAN-0001

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

5/12/2008 8:23	34,402		Camry	2007	19063
5/12/2008 13:42	5,080		Prius	2008	19063
5/12/2008 14:04	5,080		Prius	2008	19063
5/12/2008 16:06	15,332	B1801	Highlander	2008	4017
5/13/2008 5:46	637		Camry HV	2009	29102
5/13/2008 9:34	88,560		Sienna	2005	2021
5/13/2008 13:07	15,473		Camry HV	2007	4075
5/14/2008 6:21	1,319	C1288,U0073,U0100,U0126,U0129	Camry	2009	19005
5/14/2008 9:56	1,640		Tundra	2008	34077
5/15/2008 9:35	44,427	B1277	RX330	2005	60444
5/15/2008 12:52	16,637	B1242	Sienna	2007	28021
5/15/2008 12:55	67		Avalon	2008	34041
5/16/2008 11:12	37,077		Corolla	2004	13067
5/16/2008 11:57	20,308		GS350	2007	60301
5/16/2008 15:54	77,451		Camry	2004	2021
5/17/2008 16:08	15,350		Tacoma	2007	4070
5/13/2008 7:14	2,339	P0A80,P3000	Prius	2008	12071
5/13/2008 9:06	21,911	B1152,B1294,C1242,P0A08,P3108,U0129,U0131,U0146	RX400H	2006	64202
5/14/2008 9:53	84,665	P0300,P0303,P0304	Prius	2003	20090
5/14/2008 12:00	39,390	P0300,P0301,P0302,P0306	RX400H	2006	62201
5/12/2008 11:04	11,837		Corolla	2006	46081
5/12/2008 11:10	59,321	P0420	Sienna	2004	24074

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

CAT	CAT		3	INITIATED	GARY JONES	5/12/2008 0:00	Audio/Visual/Telematics
CAT	CAT		3	INITIATED	KEVIN BAUMGARDNER	5/12/2008 0:00	Audio/Visual/Telematics
CAT	CAT		3	INITIATED	KEVIN BAUMGARDNER	5/12/2008 0:00	Audio/Visual/Telematics
SFR	SFR		7	INITIATED	BRAD FARGO	5/12/2008 0:00	Vehicle Interior
NYR	NYR		5	INITIATED	RICHARD WICHROWSKIJR	5/13/2008 0:00	Vehicle Interior
DEN	DEN		6	INITIATED	TERRY ATKINSON	5/12/2008 0:00	Vehicle Interior
LOS	LOS		3	INITIATED	ALEJANDRO BANAG	5/13/2008 0:00	Audio/Visual/Telematics
CAT	CAT		2	INITIATED	DALE MCKENNA	5/7/2008 0:00	Power Source/Network
CIN	CIN	G		INITIATED	BRAD MALOTT	5/14/2008 0:00	Audio/Visual/Telematics
WES	WES		3	INITIATED	CARLOS VELASQUEZ	5/15/2008 0:00	Vehicle Interior
BOS	BOS		6	INITIATED	FLETCHER ROGERS	5/15/2008 0:00	Vehicle Interior
CIN	CIN	F		INITIATED	RICHARD ANGLES	5/15/2008 0:00	Audio/Visual/Telematics
CHI	CHI		5	INITIATED	JEFFREY ALLBRIGHT	5/16/2008 0:00	Vehicle Interior
SOU	SOU		1	INITIATED	RANDY NASH	5/16/2008 0:00	Audio/Visual/Telematics
DEN	DEN		6	INITIATED	VINCE JOHNSEN	5/16/2008 0:00	Vehicle Interior
SFR	SFR		7	INITIATED	RENE DOESS	5/17/2008 0:00	Engine/Hybrid System
CHI	CHI		5	INITIATED	ARTHUR MARTIN	5/13/2008 0:00	Engine/Hybrid System
SOU	SOU		2	INITIATED	SCOTT LEVEQUE	5/13/2008 0:00	Engine/Hybrid System
BOS	BOS		0	INITIATED	George Hoyt	5/14/2008 0:00	Engine/Hybrid System
CEN	CEN		4	INITIATED	ROBERT BELTZ	5/14/2008 0:00	Engine/Hybrid System
PTL	PTL		3	INITIATED	DARYL MILLER	5/12/2008 0:00	Engine/Hybrid System
KCY	KCY		1	INITIATED	BRIAN SWEARINGEN	5/12/2008 0:00	Engine/Hybrid System

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Audio/Video	Wireless Headphones	Poor reception/static
Audio/Video	Satellite Receiver	Poor reception/static
Audio/Video	Satellite Receiver	Poor reception/static
Supplemental Restraint Systems	Warning Light - SRS	MIL/Warning Light ON
Heating/Air Conditioning	Unknown	Leak
Heating/Air Conditioning	Unknown	Inoperative
Cellular Communication	Unknown	Noise-Abnormal
Networking	Unknown	CD/Cassette will not eject
Navigation/Multi Info Display	Nav System/Display/Components	Abnormal Operation
Heating/Air Conditioning	Automatic Climate Control	Inoperative
Theft Deterrent/Keyless Entry	Security Remote	Inoperative
Navigation/Multi Info Display	Nav System/Display/Components	Inoperative
Door Lock	ECU	Abnormal Operation
Audio/Video	Radio Receiver	Inoperative
Door Lock	Unknown	Inoperative
Starting	Unknown	Unspecified
Hybrid/Battery Control System	Unknown	MIL/Warning Light ON
Hybrid/Battery Control System	Unknown	Starting-No start
Engine Control	Driveability	Misses
Engine Control	Driveability	MIL/Warning Light ON
Emission Control	Unknown	Stalls/Quits
Emission Control	Catalytic Converter	Abnormal Operation

TOY-TQ001-00034749

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

when customer turns on rear defroster and radio is on ;station signal disappears
when driving east as per the compass, the xm will cut out. it works correctly in all other directions
when driving east as per the compass, the xm will cut out. it works correctly in all other directions
customer states srs light comes on intermittently
leak detector goes off to a small degree around expanion valve area
a/c clutch assy.melted//3rd time//
1st-06/15/2007//54015 mileage
2nd-08/07/2007//57914
cst states speaking thru speaker/mic the person on the other end hears like a marble noise.tried another phone and confirmed the problem
abs, vsc, brake, srs, lights on on dash also ac controls inop and display back light flashing.
customer complaint, nav system does not read correct position, looses location.
a/c system does not work at all, none of the control switches work, no blinking lights, on the info display only clock works and e/t shows numbers, all other displays like distance, cruise range, average do not work, there is power at all fuses and relay, everything else in the vehicle works good, i removed control unit and inspected all wires and connectors, all good. same as to the a/c amplifier unit. i swaped control panel unit from another vehicle, still the same
have high resistance d4-1 to body ground 690.10korms. when did check on ground system works now. and now resistances is 12.1 orms
navigation inop. perform system check and navi shows ncon. check connections at nav ecu and right hand side of dash (le1,le2 and dl1). connections ok. perform remote commander check and all switches normal.
wireless door lock inop., integration relay replaced for this condition 1 yr. ago for same condition. repl. relay again, no help. unable to enter registration mode for remotes. power and ground good at reciever in c pillar. voltage and continuity checks performed at integration relay
radio will not turn on. fuses are good, power is available to radio. diagnostic screen shows audio n-conn.

when cranking, a repetitive cliking noise is present at times. noise source is starter solonoid (same cond. with new starter). found pulsing 12v signal at pin 1 of sta relay. located partialy open pink wire bewteen engine room fuse box and engine. pulsing voltage generated by rocking engine while cranking. turning the solonoid on and off causes the solonoid to actibate. at times no cranking.
went to techstream to powertrain then hv batt. for codes code p0a1f was not set tells me to replace battery pack only codes set are p0a80 and p3000 any help on this car has only 2339 miles on it.
additional code u0129.
no start. car died while driving. no vim communication. no ready light. will intermit. ready on and will connect with scan tool.
vehicle was originally brought in for p3191 code. tsb was done for this code (not needed) vehicle then had cylinder 4 misfire. compression was checked, fuel pressure was checked coils, plugs, injectors were swapped. see original case ta081130288
mil on, runs fine at this time
felt like losing power, stalled while driving, restarted. no codes has had ecu calibration update already.
vehicle had converter replaced 1-17-08 p0420 and p2238 set replaced a/f sensors and reflashed per tsb eg001-05 p0420 returned

TOY-TQ001-00034750

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

TOYOTA	GARY JONES	y	JONES, GARY
TOYOTA	KEVIN BAUMGARDNER	y	BAUMGARDNER, KEVIN
TOYOTA	KEVIN BAUMGARDNER	y	BAUMGARDNER, KEVIN
TOYOTA	BRAD FARGO	y	FARGO, BRAD
TOYOTA	RICHARD WICHROWSKIJR	y	WICHROWSKIJR, RICHARD
TOYOTA	TERRY ATKINSON	y	ATKINSON, TERRY
TOYOTA	ALEJANDRO BANAG	y	BANAG, ALEJANDRO
TOYOTA	DALE MCKENNA	y	MCKENNA, DALE
TOYOTA	BRAD MALOTT	y	MALOTT, BRAD
LEXUS	CARLOS VELASQUEZ	y	VELASQUEZ, CARLOS
TOYOTA	FLETCHER ROGERS	y	ROGERS, FLETCHER
TOYOTA	RICHARD ANGLES	y	ANGLES, RICHARD
TOYOTA	JEFFREY ALLBRIGHT	y	ALLBRIGHT, JEFFREY
LEXUS	RANDY NASH	y	NASH, RANDY
TOYOTA	VINCE JOHNSEN	y	JOHNSEN, VINCE
TOYOTA	RENE DOESS	y	DOESS, RENE
TOYOTA	ARTHUR MARTIN	y	MARTIN, ARTHUR
LEXUS	SCOTT LEVEQUE	y	LEVEQUE, SCOTT
TOYOTA	George Hoyt	y	HOYT, GEORGE
LEXUS	ROBERT BELTZ	y	BELTZ, ROBERT
TOYOTA	DARYL MILLER	y	MILLER, DARYL
TOYOTA	BRIAN SWEARINGEN	y	SWEARINGEN, BRIAN

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

DARCARS TOY. OF FREDERICK	QAElectrical
DARCARS TOY. OF FREDERICK	QAElectrical
DARCARS TOY. OF FREDERICK	QAElectrical
JIMMY VASSER TOYOTA	QAElectrical
CHERRY HILL TOYOTA	QAElectrical
DESERT TOYOTA OF TUCSON	QAElectrical
KEYES TOYOTA	QAElectrical
JONES TOYOTA	QAElectrical
JOSEPH AIRPORT TOYOTA	QAElectrical
MAGNUSSEN'S LEXUS/FREMONT	QAElectrical
BILL DUBE TOYOTA	QAElectrical
GERMAIN TOY OF COLUMBUS	QAElectrical
KENNY KENT TOYOTA	QAElectrical
PARKER LEXUS	QAElectrical
DESERT TOYOTA OF TUCSON	QAElectrical
FREEMAN TOYOTA	QAElectrical
NEWBOLD TOYOTA	QAHybrid
LEXUS OF AUSTIN	QAHybrid
BOSTON REGION	QAHybrid
LEXUS OF WAYZATA	QAHybrid
FIVE STAR CHEVY/TOYOTA	QAPowertrain
JAY WOLFE TOYOTA	QAPowertrain

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

177684 NORMAL
177720 NORMAL
177720 NORMAL
11428 NORMAL
234859 NORMAL

276442 NORMAL
62441 NORMAL
547830 NORMAL
308609 NORMAL

180721 NORMAL
642829 NORMAL

32991 NORMAL

296513 NORMAL
226665 NORMAL
275458 NORMAL

706870 NORMAL

162269 NORMAL

168141 NORMAL

377060 NORMAL
291747 NORMAL
105946 NORMAL
337566 NORMAL

QAPowertrain	INITIATED	TA081330396	JTHBJ46G082[redacted]	12-May-08	5/12/2008 15:53	12-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340041	JTHCH96S560[redacted]	13-May-08	5/13/2008 6:56	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340043	JTHBL46F185[redacted]	13-May-08	5/13/2008 6:58	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340076	1NXBU40E19Z[redacted]	13-May-08	5/13/2008 7:32	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340133	JTHBJ46G272[redacted]	13-May-08	5/13/2008 9:02	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340149	4T1BE46K77U[redacted]	13-May-08	5/13/2008 9:22	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340153	4T1BF32K15U[redacted]	13-May-08	5/13/2008 9:28	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340198	JTHBJ46G472[redacted]	13-May-08	5/13/2008 10:32	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340341	JTHBJ46G582[redacted]	13-May-08	5/13/2008 13:47	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340350	5TEJU62N38Z[redacted]	13-May-08	5/13/2008 14:01	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081340351	JTHBJ46GX82[redacted]	13-May-08	5/13/2008 14:01	13-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081350025	4T1BF30K62U[redacted]	14-May-08	5/14/2008 6:21	14-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081350262	5TDZA23CX5S[redacted]	14-May-08	5/14/2008 11:55	14-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081350295	5TEUU42N47Z[redacted]	14-May-08	5/14/2008 12:41	14-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081350303	5TBDT48145S[redacted]	14-May-08	5/14/2008 12:49	14-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081350312	JTHBJ46G872[redacted]	14-May-08	5/14/2008 13:01	14-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081360075	JTHBH96S465[redacted]	15-May-08	5/15/2008 8:11	15-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370012	2T1BR32E25C[redacted]	16-May-08	5/16/2008 6:04	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370050	JTDBL40E699[redacted]	16-May-08	5/16/2008 7:17	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370079	JTHBH96S365[redacted]	16-May-08	5/16/2008 8:00	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370118	JT8UF11E6N0[redacted]	16-May-08	5/16/2008 8:53	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370127	JTHBJ46G072[redacted]	16-May-08	5/16/2008 9:05	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370160	5TFRV54167X[redacted]	16-May-08	5/16/2008 10:05	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370215	5TDZK23C88S[redacted]	16-May-08	5/16/2008 11:59	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081370324	JT2AE09B0S0[redacted]	16-May-08	5/16/2008 16:18	16-May-08	01-JAN-0001

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

5/12/2008 15:53	519	P0031,P2238	ES350	2008	60438
5/13/2008 6:56	38,826	P0301,P0305	GS300	2006	63130
5/13/2008 6:58	5,048	P0335	LS460	2008	63231
5/13/2008 7:32	163	P0015	Corolla	2009	44014
5/13/2008 9:02	16,075		ES350	2007	60901
5/13/2008 9:22	28,855		Camry	2007	20125
5/13/2008 9:28	49,321		Camry	2005	26024
5/13/2008 10:32	15,151		ES350	2007	64802
5/13/2008 13:47	1,557	P043E,P043F,P2401,P2402,P2419	ES350	2008	64207
5/13/2008 14:01	456		Tacoma	2008	4353
5/13/2008 14:01	11,340		ES350	2008	60603
5/14/2008 6:21	63,373		Camry	2002	38025
5/14/2008 11:55	24,595		Sienna	2005	20019
5/14/2008 12:41	28,113		Tacoma	2007	43016
5/14/2008 12:49	29,336		Tundra	2005	26012
5/14/2008 13:01	14,541		ES350	2007	61930
5/15/2008 8:11	44,857		GS300	2006	64204
5/16/2008 6:04	66,164	C2103	Corolla	2005	19057
5/16/2008 7:17	446	P0171,P0441,P0455	Corolla	2009	16049
5/16/2008 8:00	26,077	P0751	GS300	2006	64204
5/16/2008 8:53	224,267		LS400	1992	64232
5/16/2008 9:05	16,269	P0121,P0123,P2135	ES350	2007	60402
5/16/2008 10:05	17,308		Tundra	2007	4290
5/16/2008 11:59	31,431		Sienna	2008	34050
5/16/2008 16:18	142,968		Corolla	1995	5059

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

WES	WES		2	INITIATED	JULIO LUZA	5/9/2008 0:00 Engine/Hybrid System
EAS	EAS		3	INITIATED	JULES DESROSIERS	5/13/2008 0:00 Engine/Hybrid System
SOU	SOU		5	INITIATED	RICHARD KING	5/12/2008 0:00 Engine/Hybrid System
BOS	BOS		5	INITIATED	ROBERT CORBIN	5/13/2008 0:00 Engine/Hybrid System
SOU	SOU		4	INITIATED	STUART KIDDER	5/13/2008 0:00 Drivetrain
BOS	BOS		4	INITIATED	DEREK SIMMONS	5/12/2008 0:00 Engine/Hybrid System
KCY	KCY		5	INITIATED	NATE WEILER	5/12/2008 0:00 Drivetrain
CEN	CEN		4	INITIATED	MICHAEL MCCOIC	4/13/2008 0:00 Engine/Hybrid System
SOU	SOU		1	INITIATED	SHANE MORRELL	5/13/2008 0:00 Engine/Hybrid System
LOS	LOS		9	INITIATED	JOSEPH PETER	5/13/2008 0:00 Drivetrain
EAS	EAS		2	INITIATED	SAL CIRILLO	5/13/2008 0:00 Engine/Hybrid System
BOS	BOS		3	INITIATED	PHILLIP RICHARDSON	5/14/2008 0:00 Engine/Hybrid System
BOS	BOS		1	INITIATED	RODNEY DUKES	5/14/2008 0:00 Engine/Hybrid System
DEN	DEN		4	INITIATED	KELLY JAQUIER	5/14/2008 0:00 Drivetrain
KCY	KCY		5	INITIATED	THOMAS NODEN	5/14/2008 0:00 Engine/Hybrid System
EAS	EAS		6	INITIATED	MICHAEL DURAND	5/14/2008 0:00 Drivetrain
SOU	SOU		1	INITIATED	OMAR MACIAS	5/15/2008 0:00 Engine/Hybrid System
CAT	CAT		3	INITIATED	GHOLAM MAKAREHCHI	5/16/2008 0:00 Engine/Hybrid System
CIN	CIN	I		INITIATED	EUGENE STAGNER	5/16/2008 0:00 Engine/Hybrid System
SOU	SOU		1	INITIATED	JAMIE SMITH	5/16/2008 0:00 Drivetrain
SOU	SOU		1	INITIATED	TRAVIS REED	5/16/2008 0:00 Drivetrain
WES	WES		2	INITIATED	VINCENT CABACUNGAN	5/13/2008 0:00 Engine/Hybrid System
LOS	LOS		8	INITIATED	JEREMIAH HURNBLAD	5/16/2008 0:00 Drivetrain
CIN	CIN	E		INITIATED	RUSSELL SHERIFF	5/16/2008 0:00 Drivetrain
DEN	DEN		2	INITIATED	DAVID SWEETJR	5/16/2008 0:00 Engine/Hybrid System

TOY-TQ001-00034756

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Engine Control	ECU	MIL/Warning Light ON
Engine Control	Unknown	MIL/Warning Light ON
Engine Control	Driveability	Runs Rough
Engine Control	Unknown	MIL/Warning Light ON
Automatic Transmission/Transaxle	Shift Function	Abnormal Operation
Engine Mechanical	Fluid	Condition-Not-Listed
Automatic Transmission/Transaxle	Shift Function	Vibration
Engine Control	Driveability	Abnormal Operation
Emission Control	Unknown	MIL/Warning Light ON
Axle/Differential	Unknown	Noise-Abnormal
Emission Control	Unknown	MIL/Warning Light ON
Fuel System	Unknown	Surge
Engine Control	Driveability	Condition-Not-Listed
Axle/Differential	Unknown	Noise-Abnormal
Engine Mechanical	PS Belt	Noise-Abnormal
Automatic Transmission/Transaxle	Shift Function	Engagement/slippage
Fuel System	Fuel Line	
Engine Control	Driveability	Stalls/Quits
Engine Control	Driveability	MIL/Warning Light ON
Automatic Transmission/Transaxle	Unknown	Comfort/feel
Automatic Transmission/Transaxle	Shift Function	Abnormal Operation
Engine Control	Driveability	Stalls/Quits
Drive Shaft/Propeller Shaft	Unknown	Noise-Abnormal
Automatic Transmission/Transaxle	Shift Function	Engagement/slippage
Engine Control	Driveability	Hesitation/Stumble

TOY-TQ001-00034757

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

warning light on. a/f sensor 1 bank 1 was replaced with no
success.
customer states mil light is on
customer states that the vsc light came on and the engine began running rough.
i have code p0015 camshaft postion "b" timing over retarded (bank 1) no other codes present i active tested vvt exhaust linear (bank1) after clearing the codes and the engine runs rough but dosen't stall, i checked the resitance of the oil control actuator and had 8.1 ohms jumped it with 12volts and it move very quickly i'm going to drive in check mode next and see if it comes back
customer complain of shift flare when cold, worse between 4-5. has been reflashed for same concern.
tow in. engine seized, rod broken, wrist pin through side of engine. piston pushed up into cyl head.

low speed shake. vibration in 1st and 2nd gear under small load. vibration is not felt in reverse. can duplicate with vehical on host and off the ground
customer states the vehicle was stuck on wot drove a few blocks tryiing to lift pedal with his foot. shut vehicle off and restarted normal operation after restart.
codes stored in memory. cleared and retested, codes reappeared after automatic test.
rear differential assymbly mounting nuts all loose, lost fluid, differential gears severly damaged
ck eng light on 4th time code po172 and po175
no codes under light acceleration car bucks
c/s rotten egg smell, switched to super fuel and condition still exists
front differential making noise 30 to 50 mph, goes away in 4wd, replaced front diff once before, noise was gone, now making noise agian
perform tsb eg026-06 and nose still present, anything other causing belt noise? all pulleys are staight and alignment is good.
cust states trans slipping trans was repl at dealer in fla. no dtc no avial reflash fld level was 3 pints low per fld level insp procedure released vehicle pls close case
corrosion in lines
car shuttes off while driving.intermitnly. last time in rode tested for over 30 miles and did not duplicate.throttle has been replaced by another dealer

customer stated transmission stuck in fourth gear. customer pulled over stopped and car started shifting normally afterward.
car would not down shift, replaced tps and now it does. car now skips 2nd gear after downshift.
while driving car will shake and turn off
clunk noise intermitant when braking
cust states periodically veh seems to go into neutral or hesitates a very long time when turning corner and try to accel.[no codes stored test drove w/cust could not get problem to accure fluid level correct]
engine stumbles when you rev it up too fast. it can be lightly accelerated up to speed without any problem.only occurs after engine reaches proper operating temperature. eliminated possible fuel pressure, ignition and timing problems. attached scan tool through breakout box and inspected 02 sensor wave form. when symptom acts up the o2 sensor reads lean. at idle the o2 sensor wave form is sluggish and sometimes just shows lean. symptom also occurs with o2 sensor disconnected.

TOY-TQ001-00034758

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

LEXUS	JULIO LUZA	y	LUZA, JULIO
LEXUS	JULES DESROSIERS	y	DESROSIERS, JULES
LEXUS	RICHARD KING	y	KING, RICHARD
TOYOTA	ROBERT CORBIN	y	CORBIN, ROBERT
LEXUS	STUART KIDDER	y	KIDDER, STUART
TOYOTA	DEREK SIMMONS	y	SIMMONS, DEREK
TOYOTA	NATE WEILER	y	WEILER, NATE
LEXUS	MICHAEL MCCOIC	y	MCCOIC, MICHAEL
LEXUS	SHANE MORRELL	y	MORRELL, SHANE
TOYOTA	JOSEPH PETER	y	PETER, JOSEPH
LEXUS	SAL CIRILLO	y	CIRILLO, SAL
TOYOTA	PHILLIP RICHARDSON	y	RICHARDSON, PHILLIP
TOYOTA	RODNEY DUKES	y	DUKES, RODNEY
TOYOTA	KELLY JAQUIER	y	JAQUIER, KELLY
TOYOTA	THOMAS NODEN	y	NODEN, THOMAS
LEXUS	MICHAEL DURAND	y	DURAND, MICHAEL
LEXUS	OMAR MACIAS	y	MACIAS, OMAR
TOYOTA	GHOLAM MAKAREHCHI	y	MAKAREHCHI, GHOLAM
TOYOTA	EUGENE STAGNER	y	STAGNER, EUGENE
LEXUS	JAMIE SMITH	y	SMITH, JAMIE
LEXUS	TRAVIS REED	y	REED, TRAVIS
LEXUS	VINCENT CABACUNGAN	y	CABACUNGAN, VINCENT
TOYOTA	JEREMIAH HURNBLAD	y	HURNBLAD, JEREMIAH
TOYOTA	RUSSELL SHERIFF	y	SHERIFF, RUSSELL
TOYOTA	DAVID SWEETJR	y	SWEETJR, DAVID

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

JIM FALK LEXUS OF	QAPowertrain
LEXUS OF ROCKVILLE CENTRE	QAPowertrain
JOHNSON LEXUS OF DURHAM	QAPowertrain
HERITAGE TOYOTA	QAPowertrain
LEXUS OF TAMPA BAY	QAPowertrain
ROUTE 44 TOYOTA	QAPowertrain
PERFORMANCE TOYOTA-SCION	QAPowertrain
LEXUS OF MADISON	QAPowertrain
PARK PLACE LEXUS	QAPowertrain
TOYOTA CHULA VISTA	QAPowertrain
LEXUS OF GREENWICH	QAPowertrain
VALENTI TOYOTA	QAPowertrain
TOYOTA OF WATERTOWN	QAPowertrain
LARRY H. MILLER TOYOTA	QAPowertrain
OLD MILL TOYOTA	QAPowertrain
LEXUS OF TOWSON	QAPowertrain
SEWELL LEXUS	QAPowertrain
355 TOYOTA	QAPowertrain
TOYOTA SOUTH, INC.	QAPowertrain
SEWELL LEXUS	QAPowertrain
PARK PL. LEXUS GRAPEVINE	QAPowertrain
LONGO LEXUS	QAPowertrain
TOYOTA OF SANTA MARIA	QAPowertrain
GRAHAM TOYOTA	QAPowertrain
LIBERTY TOYOTA-SCION	QAPowertrain

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

196402	NORMAL
295333	NORMAL
243775	NORMAL
308938	NORMAL
834205	NORMAL
361963	NORMAL
162821	NORMAL
115227	NORMAL
686467	NORMAL
49556	NORMAL
481664	NORMAL
142339	NORMAL
181572	NORMAL
374464	NORMAL
277878	NORMAL
83922	NORMAL
1407126	NORMAL
801666	NORMAL
136336	NORMAL
1407365	NORMAL
827985	NORMAL
95310	NORMAL
225150	NORMAL
268324	NORMAL
255445	NORMAL

TOY-TQ001-00034761

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

QAPowertrain	INITIATED	TA081370331	5TEHN72N62Z[redacted]	16-May-08	5/16/2008 17:28	16-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081380002	4T1BE46K07U[redacted]	17-May-08	5/17/2008 10:58	17-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081380003	5TENX22N18Z[redacted]	17-May-08	5/17/2008 11:21	17-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081380004	JTHCK262972[redacted]	17-May-08	5/17/2008 12:41	17-May-08	01-JAN-0001
QAPowertrain	INITIATED	TA081380007	JTMBK31V865[redacted]	17-May-08	5/17/2008 16:39	17-May-08	01-JAN-0001

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

5/16/2008 17:28	52,036	P0420	Tacoma	2002	20053
5/17/2008 10:58	2,288		Camry	2007	46067
5/17/2008 11:21	5,243		Tacoma	2008	4061
5/17/2008 12:41	44,655	P0171,P0174	IS250	2007	61301
5/17/2008 16:39	29,710		RAV4	2006	4282

TOY-TQ001-00034763

BOS	BOS	2	INITIATED	STEVEN ORANELLAS	5/16/2008 0:00	Engine/Hybrid System
PTL	PTL	2	INITIATED	RICHARD REICHENBACH	2/5/2008 0:00	Drivetrain
LOS	LOS	7	INITIATED	GUY FRANZEN	5/17/2008 0:00	Drivetrain
CEN	CEN	2	INITIATED	KENNETH HOWARD	5/16/2008 0:00	Engine/Hybrid System
LOS	LOS	9	INITIATED	PATRICK HARTLEY	5/17/2008 0:00	Engine/Hybrid System

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

Emission Control	Catalytic Converter	Abnormal Operation
Automatic Transmission/Transaxle	Unknown	Vibration
Automatic Transmission/Transaxle	Shift Function	Vibration
Engine Control	Driveability	MIL/Warning Light ON
Engine Control	Unknown	Starting-No start

TOY-TQ001-00034765

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

history-p1135-af sensor done.
then a p0420, front cat was done. p0420 again,rear cat was done. p0420 again. ck.compression.- 185-195 all across.
02 tests good. @ 3000 rpm, voltage never completely flat lines and @ times, voltage will hang @ 650 mv ,then suddenly drop and hang around 450 mv , and back a gain, but never really flat lines. slight engine roughness at idle. perform toyota fuel inj. flush and will get back with the results of retesting the cats.
light to mid acceleration through 35-45 mph, there is a vibration that feels like a bad tire/seperated belt. have changed tires, and swapped wheels and tires from known good unit, no change. seems to stop when in nuetral?
after 2nd to 3rd shift rpm will go from 2k to 1k and there is a vibration during low speeds between 20 to 30mph

cust states veh wont crank/wont start intermitt. then if they shift into nuetral , veh will start. checked pins at n safety switch- good , battery good

TOY-TQ001-00034766

TOYOTA	STEVEN ORANELLAS	y	ORANELLAS, STEVEN
TOYOTA	RICHARD REICHENBACH	y	REICHENBACH, RICHARD
TOYOTA	GUY FRANZEN	y	FRANZEN, GUY
LEXUS	KENNETH HOWARD	y	HOWARD, KENNETH
TOYOTA	PATRICK HARTLEY	y	HARTLEY, PATRICK

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION

BOCH TOYOTA, INC.	QAPowertrain
TITUS-WILL TOY. SALES INC	QAPowertrain
TOYOTA OF SAN BERNARDINO	QAPowertrain
TOM WOOD LEXUS	QAPowertrain
TOYOTA OF ESCONDIDO	QAPowertrain

TOY-TQ001-00034768

528190 NORMAL

528194 NORMAL
541599 NORMAL
116453 NORMAL
399096 NORMAL

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION